



Austin-Healey Parts List



Quantity	Part Number	Description	Price Each
		Austin-Healey 100 NOS PARTS fits BN2 and Lemans (not BN1)	
16-18	AEC2186	GB Needle Bearings to MKII	\$0.55
1	AEB3203	GB Layshaft	\$100.00
1	AEC3210	GB 2nd Gear	\$250.00
1	0247A/02420	Front Pinion Bearing - Rear Axle	\$50.00
1	AEC3107	GB Reverse Wheel	\$125.00
1	AEC3003	GB Reverse wheel BN2, BN4, BN6	\$125.00
2	3478/3402	Rear Pinion Bearing - Rear Axle	\$50.00
2	46893	Borg & Beck Clutch Release Bearing	\$60.00
2	31042	Lucas Throttle OD Switch/Relay	sold
1	SP1963/3	Girling Master Cylinder Kit	\$35.00
3	SP2018/1	Girling Wheel Cylinder Kit	\$25.00
1	371062	Girling Flex Brake Hose (2A7227)	\$30.00
1	SP2024	Girling Rear Wheel Cylinder Kit (Axle) (8G8024) to MKI	\$40.00
2	2H979	Cold Air Box Strip & Buckle Clip	sold
1	2K5507	Steyr GB Rear Bearing	\$50.00
2	ATC7262	Differential Bearing	\$60.00
1	57052	Lucas Reflector Unit (Pr.)(57124)	sold

1	1B4400	Front Hub - Outer Taper Roller Bearing (set)	\$50.00
1	8G554	Front Hub Oil Seal	\$20.00
1		Austin-Healey Sprite Amco Tonneau, cream, MKI, short fit	\$75.00
1	1042	Amco Austin Healey 100 soft top NOS in box-Black	\$250.00
1 set		Amco Austin Healey floor mats w/ emblem NOS in box-Black fits all	\$95.00
		Austin-Healey 100 TOOLS for tool kit-see photos-have all items-list needs	inquire
		Miscellaneous Parts	
6		Austin-Healey 3000 MKIII octogon knockoffs 4-L, 2-R, wrench	\$30.00 ea
4		Austin-Healey 300 MKI-II, III eared knockoffs 2-L, 2-R coarse thread	\$40.00ea
1	1B3694	Austin-Healey 100-4 transmission 1st motion shaft #5146on later box- NOS	\$450.00
		Austin Healey Gaskets/etc.	
2	HC005	Halls sump set 6 cylinder sump and main BRG cap	\$25.00 ea
2	AEC827	Factory NOS steel headgasket 6 cylinder, eearly 100-6	\$50.00 ea
1	C82A329	MKI Sprite MK4 conversion set (midget 3) 1275 cc "Payen"	\$22.00
1	GEG239	Unipart Sprite MKII conversion set 1098 cc	\$25.00
2	TS20005	Best transmission gasket set 100-6, 56-8 BN6-58-59	\$15.00
2	TS20005	Payen transmission gasket set 100-4 BN2, 100-6 with overdrive	\$15.00
2		Austin-Healey 100-3000 disc wheel hubcaps w/"A"	\$100.00
5 sets	A Series eng.	Altron (Italy) 141-1004 points, 141-2070 condenser, 141-3010 rotor (set of 3)	\$10.00/set

		Austin Healey Literature	
Parts	100-6	BN4 service parts list with binder NOS	\$90.00
	3000	BN7-BT7 MKI service parts list with binder NOS	\$110.00
	ADK829 (5th)	Sprite service parts list with binder AKD 1575 Good/Excellent condition	\$60.00
	1207 (10-55)	A-90 six binder, excellent condition	\$140.00
Service			
	997B (9-54)	Austin-Healey 100-4 BN1 H.B., cover defect	\$45.00
	97H 1489	A-H 100-6 BN4 with binder	\$35.00
Driver	996D	February 1955 100-4 H.B. owners manual, exact reproduction	\$35.00
	97H1583 (4-58)	Sprite AN5 early, good, binder drilled	\$65.00
	97H1583	Sprite AN5, early-rough cover	\$50.00
	97H1583	Sprite AN5 early-excellent	\$100.00
	AKD1627A (3-60)	Sprite MKI and MKII, condition B+	\$40.00
	97H1583	Sprite AN5 DMH signed, cover missing, reprint	\$10.00
	1040 (F)	100-4 Four color, 12 page, condition c	sold
Sales	1172	100-S Two color, 8 page, original, condition A-	sold
(in binder)	1172	100-S Two color, 8 page, original, conditon B	sold
	1405	100-6 Color, 4 page, 1st edition, condition C+ (fold)	\$30.00

